


**9.3** Connect the HDD SATA cable and HDD SATA power cable




**10. Assemble the slim ODD**

**10.1** Assemble the ODD metal bracket into chassis and fix these three screws




Step	Screw	Quantity	Screw Type	Part Number	Torque/ kgfcm
Slim ODD bracket	#6-32*5mm	3pcs		N/A	6.0~7.0Kgf/cm


**10.2** Assemble the bezel



10.3 Assemble the slim ODD into the chassis



10.4 Connect the ODD SATA cable and ODD SATA power cable




11. Cable routing position



---

12. Assemble the side cover and fix two screws of left side cover



Step	Screw	Quantity	Screw Type	Part Number	Torque/ kgfcm
side cover	#6-32*5mm	2pcs		N/A	6.0~7.0Kgf/cm