
Prepared by: James Soler



Observations:

Night Setback: How come both day and night time HWS(Heating Water System) temperatures are the same? Program night temp 10 Deg lower.

Delay turning heat on when temperature is below Setpoint. Possible correction adjusting settings?

Equipment and Setting: Verify Panel assesorties set up. I see we have Heat-Timer Platinum Controller. I've downloaded Manual and would like to review.

Overall Observation: We have a very good system which is **basically self balancing**. By downloading real time data we can do what a super, mechanic or exsisting control cannot do. That is "**Data Driven Perormance Analyses.**" Fuel Savings, Even Temperatures, Customer Satisfaction.