ZYXEL

Zyxel

Firmware Release Note

WSR30

Release V1.00(ABMY.11)C0

ZYXEL

WSR30
Release V1.00(ABMY.11)C0

Release Notes

Date: Aug 20, 2020

Supported Platforms:

Zyxel WSR30

Release Package:

File name	Description
V1.00(ABMY.11)C0.bin	WSR30 Firmware Package for standard version
V1.00(ABMY.11)C0.pdf	Firmware release note

Features
Enhancement in V1.00(ABMY.11)C0 | 08/20/2020
[Bug Fix]
1. Diagnose > Speed Test > Tap Test, then get stuck in the upload

Enhancement in V1.00(ABMY.10)C0 | 03/12/2020
[Enhancement]
1. Apply ppp-2.4.7 security vulnerability issue.

[Bug Fixed]
1. Fix client cannot access internet through guest Wi-Fi network in bridge mode.

Enhancement in V1.00(ABMY.9)C0 | 12/23/2019
[Enhancement]
1. Enhance tri-band AP when only one device installed.
2. Enhance abnormal issue cause system unstable.

Enhancement in V1.00(ABMY.8)C0 | 10/7/2019

[Enhancement]
1. AP steering mechanism improve for sometimes client does not roam to DUT properly.
2. LED behavior update when WiFi 5G low band disconnected in EU version.

[Bug Fixed]
1. Fix sometimes firmware upgrade finished but not reboot issue

Enhancement in V1.00(ABMY.7)C0 | 7/29/2019

[Bug Fixed]
1. Fix IOS minecraft gaming app login procedure takes long time.
2. Fix sometime diagnose WiFi Signal check function cannot work.

Enhancement in V1.00(ABMY.6)C0 | 5/31/2019

[Enhancement] Enhance LED dimming via LED button.

Enhancement in V1.00(ABMY.5)C0 | 3/15/2019

[Enhancement] Enhance DFS mechanism.

Enhancement in V1.00(ABMY.1)C0 | 9/13/2018

[Initial Version]