


## Heating System (Continued)

8. Repair/ Replace Distribution: Metal duct - **Replace the missing register at the steps to the basement.**



9. Acceptable Flue Pipe: PVC pipe  
Basement Heating System
- 
10. Manufacturer: American Standard



11. Marginal

Heating System Operation: Appears functional - The steam boiler has to be filled manually every week during the heating season and drained weekly. Upcoming repairs may include replacing the steel return lines along the basement floor.

