



1. REMOVE ALL BURRS AND SHARP EDGES.
2. UNDIMENSIONED RADII TO BE .13.



UNLESS OTHERWISE SPECIFIED, DIMENSIONS ARE IN INCHES .XX = ±.0- .XXX = ±.00- .XXXX = ±.000- SURFACE FINISH 		NAME	DATE	<h1>Exercise 4</h1>					
	DRAWN	FastwayJim	06/06/2016				TITLE		
	CHECKED								
	APPROVED								
DO NOT SCALE DRAWING				SIZE B DWG NO. REV. -					
BREAK ALL SHARP EDGES AND REMOVE BURRS									
THIRD ANGLE PROJECTION	MATERIAL	FINISH	SCALE WEIGHT SHEET 1 of 1						
