

ZYXEL

Firmware Release Note

WSQ20

Release V1.00(ABOF.9)C0

WSQ20 Release V1.00(ABOF.9)C0

Release Notes

Date: Aug. 11, 2020

Supported Platforms:

Zyxel WSQ20

Release Package:

File name	Description
V1.00(ABOF.9)C0.bin	WSQ20 Firmware Package for standard version
V1.00(ABOF.9)C0.pdf	Firmware release note

Features

Enhancement in V2.20(ABOF.9)C0 | 08/11/2020

[Bug Fix]

- Diagnose > Speed Test > Tap Test, then get stuck in the upload.

Enhancement in V2.20(ABOF.8)C0 | 03/05/2020

[Bug Fixed]

- Update notification software

Enhancement in V1.00(ABOF.7)C0 | 01/07/2020

[Enhancement]

- Press "Topology refresh" button will release the restriction of forcing backhaul connected on 2.4G.

[Bug Fix]

- Fix stability issue.

Enhancement in V1.00(ABOF.6)C0 | 10/07/2019

[Bug Fix]

- Fix stability issue.

Enhancement in V1.00(ABOF.5)C0 | 08/20/2019

[Enhancement]

- Ethernet backhaul.

Enhancement in V1.00(ABOF.4)C0 | 06/17/2019

[Bug Fix]

- Fix LED error when system bootup.

Enhancement in V1.00(ABOF.2)C0 | 03/15/2019

[Bug Fix]

- Fix some bugs.

Enhancement in V1.00(ABOF.1)C0 | 02/25/2019

[Bug Fix]

- Fix some bugs.

Enhancement in V1.00(ABOF.0)C0 | 01/24/2019

[Initial Version]