

A close-up photograph of a metal rim, likely part of a combustion chamber. The rim is made of a dark, possibly cast iron or steel, material and shows signs of wear, including scratches and discoloration. A red arrow points from a text box to the rim. In the background, a white cylindrical object and a metal flange with a bolt are visible.

this rim keeps the refractory from
falling down into combustion
chamber which is smaller
diameter.